



**Department of
Environmental
Conservation**

DEC CPWG Site Update

Hoosick Area Investigations

February 22, 2022

Site Updates

- River Road
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442008>
 - The following were submitted to the department
 - Draft Site Characterization Report
 - IRM pre-design investigation (PDI) workplan
 - Both Documents are under review
- Hoosick Falls Landfill
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442007>
 - A Remedial investigation report is being prepared to summarize the work completed in 2021



Site Updates

- Columbia Corp
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442005>
 - Revised Site Characterization Report is under review.
- John Street
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442049>
 - Remedial investigation has been reviewed and comments have been issued to the RP.
- Interface Solutions
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442059>
 - Site Characterization Report was received and is under review



Site Updates

- McCaffrey Street
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442046>
 - OU1 Remedial Investigation Work Plan is under review
 - OU3 remedial investigation scope is being planned, work plan expected in the spring.
 - Risk assessments are still underway with summary reports expected later this year.
- Liberty Street
 - <https://gisservices.dec.ny.gov/gis/dil/index.html?rs=442048>
 - NYSDEC recently approved the workplan for the Interim remedial measure on the stormwater drainage system at Liberty. A fact sheet will be issued, and the workplan will be posted in the repository.
 - Additional surface water characterization work was proposed in offsite areas, that work plan was approved and work is ongoing.



Thank You

- Ian Beilby, P.E.
ian.beilby@dec.ny.gov
- Barbara Firebaugh, P.G.
barbara.firebaugh@dec.ny.gov
- Chris Monaco, P.G.
christopher.monaco@dec.ny.gov

Phone: 518.402.9676



**Department of
Environmental
Conservation**